

**2007 PZ50W PHAZER, FXW PHAZER FX, GTW PHAZER GT, MW PHAZER MOUNTAIN LITE, VTW VENTURE LITE
FACTORY MODIFICATION CAMPAIGN – Steering Idler Arm Nut
Yamaha Technical Bulletin S2007-006R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has determined a defect relating to motor vehicle safety exists in all 2007 Phazer, Phazer FX, Phazer GT, Phazer Mountain Lite, and Venture Lite model snowmobiles.

Affected Models

All 2007 PZ50W, Phazer

All 2007 PZ50FXW, Phazer FX

All 2007 PZ50GTW, Phazer GT

All 2007 PZ50MW, Phazer Mountain Lite

All 2007 PZ50VTW, Venture Lite

The reason for this recall: In affected snowmobiles, the clevis type pins used to prevent the steering idler arm nuts from falling off could dislodge. Without these clevis pins in place, the idler arm nuts could fall off if they become loose. If both nuts fall off, steering components could come apart, resulting in loss of steering control and a vehicle crash possibly resulting in injury or death.

What Yamaha and your dealer will do: To correct this possible defect, Yamaha is initiating a Factory Modification Campaign in cooperation with the U.S. Consumer Product Safety Commission. Affected snowmobiles must have the steering idler arm bolts, nuts, and collars replaced, the bolts tightened to a new torque specification, and the clevis type pins replaced with cotter pins. There will be no charge to you for this procedure.

What you should do now: Snowmobiles that are affected should not be operated until they are modified.

If you are not the first owner of the snowmobile, and are unsure if this important modification has been done, contact any authorized Yamaha Snowmobile Dealer to check. Any authorized Yamaha Snowmobile Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.