

**2003 SR230 (SRT1000-B, C-B)
FACTORY MODIFICATION CAMPAIGN – Fuel Hose Clamps
Yamaha Technical Bulletin SB2003-005**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, USA has decided that a possible defect relating to safety may exist in certain 2003 model SR230 (SRT1000-B and C-B) Sport Boats. This bulletin was originally issued on July 18, 2003.

Affected Models

2003 SRT1000-B “SR230” F1C-700101 ~ 700452

2003 SRT1000C-B “SR230” California Model F1C-750101 ~ 750200

The reason for this recall: On affected units, incorrect hose clamps may have been used to secure the fuel tank vent hose and fuel tank vent check valve. In addition, the fuel tank vent check valve may have burrs on the plastic fittings which could prevent proper sealing. Because the incorrect clamps cannot be tightened to the proper specification and burrs on the fitting could prevent proper sealing, there is a possibility of a fuel leak into the boat. If leaking fuel or its vapor is exposed to an ignition source, there is a possibility of fire or explosion with resulting personal injury or death.

What Yamaha and your dealer will do: To correct this possible defect, Yamaha is initiating a Factory Modification Campaign. All units in the affected range must have the three hose clamps replaced with new ones. There will be no charge to the customer for this procedure.

What you should do now: Do not operate your boat until this important modification is performed.

If you are not the first owner of the boat, and are unsure if this modification has been done, contact any authorized Yamaha Marine Dealer to check. Any authorized Yamaha Marine Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.