

**2004 FX1100/1100A
FACTORY MODIFICATION CAMPAIGN – Wire Harness
Yamaha Technical Bulletin WR2004-004**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a defect relating to vehicle safety may exist in certain 2004-model FX High Output “FX1100” and FX Cruiser High Output “FX1100A” WaveRunner® watercraft. This bulletin was originally released on April 16, 2004.

Affected Models

FX1100-C F1S-0800101 ~ 0802200

FX1100A-C F1S-0800201 ~ 0802300

FX1100AC-C F1S-0801401 ~ 0802100

The reason for this recall: In affected units, the main wire harness may not be properly secured, which could allow it to rub against the motor mount until the insulation is worn through. If this happens, there is a risk of a spark which could cause fire or explosion if fuel vapors are present, possibly resulting in personal injury to the operator, passengers, or bystanders.

What Yamaha and your dealer will do: To correct this possible defect, Yamaha is initiating a Factory Modification Campaign. All units in the affected range must have the main wire harness inspected and the clamp bands tightened with the wire harness in the correct position. If the harness is damaged, it must be replaced. There will be no cost to the customer for this inspection/repair.

What you should do now: Do not operate affected WaveRunner watercraft until they are inspected/modified.

If you are not the first owner of the watercraft and are unsure if this modification has been done, contact any authorized Yamaha Motorsports Dealer to check. Any authorized Yamaha Motorsports Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.