

**All 2008 FX1800-G/A-G and Certain 2009 FX1800-H/A-H
FACTORY MODIFICATION CAMPAIGN – New Fuel Hose
Yamaha Technical Bulletin WR2008-004R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a defect relating to vehicle safety may exist in all 2008 FX1800-G/A-G and Certain 2009 FX1800-H/A-H WaveRunner® watercraft. This bulletin was originally released on November 13, 2008.

Affected Models

All 2008 FX1800-G (FX SHO)/ A-G (FX Cruiser SHO)
2009 FX1800-H (FX SHO)/ A-H (FX Cruiser SHO): HIN Range: F1W-809301~815100

The reason for this recall: In the affected watercraft, there is the potential for the fuel hose to come loose from the connector at the fuel injection rail on the engine. If this happens, fuel could spray into the engine compartment, which could cause a fire or explosion resulting in severe injury or death.

What Yamaha and your dealer will do: Yamaha is initiating a Factory Modification Campaign in cooperation with the U.S. Coast Guard. A new fuel hose assembly must be installed that has a different connector and an additional clamp to provide a secure connection and eliminate the possibility of the hose coming loose.

What you should do now: Do not operate affected WaveRunner watercraft until they are modified. If you are not the first owner of the watercraft and are unsure if this modification has been done, contact any authorized Yamaha Motorsports Dealer to check. Any authorized Yamaha Motorsports Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.