

**2008 212X (FAT1100A-G / AGL)  
FACTORY MODIFICATION CAMPAIGN – Bimini Top  
Yamaha Technical Bulletin B2008-002R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, USA has decided that a possible defect relating to safety may exist in certain 2008 model 2008 212X (FAT1100A-G / AGL) Boats. This bulletin was originally issued on August 15, 2008.

**Affected Models:**

All 2008 212X models.

**The reason for this recall:** In the affected boats, there is the potential for the Bimini top to collapse, if it is in the deployed position while the boat is underway. If this happens, the top could strike the operator and or passenger and obstruct the driver's view, which could result in loss of control and an accident with injury or death.

**What Yamaha and your dealer will do:** To correct this possible defect, Yamaha is initiating a Factory Modification Campaign in cooperation with the U.S. Coast Guard. New parts, including additional support poles on each side, must be installed to provide proper support and eliminate the possibility of collapse.

**What you should do now:** Do not operate your boat until this important modification is performed.

If you are not the first owner of the boat, and are unsure if this modification has been done, contact any authorized Yamaha Marine Dealer to check. Any authorized Yamaha Marine Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.