

**2007 AND 2008 AR230 HO, SR230 HO, AND SX230 HO
Factory Modification Campaign – Extraneous Bolts Near Throttle Bodies
Yamaha Technical Bulletin B2007-006R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has determined that two separate possible defects which relate to safety may exist in certain AR230 HO, SR230 HO, and SX230 HO (SXT1100 model) Boats.

This bulletin was originally issued on December 20, 2007.

Affected Models:

2007 SXT1100C-F	AR230 HO (Black)	F2A-0730101~0730726
2007 SXT1100D-F	AR230 HO (Orange)	F2A-0740101~0740526
2007 SXT1100-F	SR230 HO (Blue)	F2A-0700101~0700156
2007 SXT1100A-F	SX230 HO (Blue)	F2A-0710101~0710569
2007 SXT1100B-F	SX230 HO (Gray)	F2A-0720101~0720574
2008 SXT1100DLG	AR230 HO (Blue)	F2A-0711317 (single unit)
2008 SXT1100A-G/ALG	AR230 HO (Black)	F2A-0731001~0731193
2008 SXT1100B-G	AR230 HO (Orange)	F2A-0741001~0741222
2008 SXT1100D-G	SX230 HO (Blue)	F2A-0711201~0711315
2008 SXT1100C-G/CLG	SX230 HO (Red)	F2A-0751001~0751160
2008 SXT1100E-G/ELG	SX230 HO (Black)	F2A-0761001~0761180

The reason for this recall: In affected boats, the fuel tank filler hose may not be installed correctly on to the filler neck from the factory. If the filler hose is not installed correctly with the hose clamps tightened in proper position, the hose can come off during refueling and allow the fuel to spill into the under seat storage compartment resulting in possible risk of a fire or explosion.

Also, in affected boats, there is a possibility that, during the boat manufacturing process, one or more bolts may have fallen into the air box near the throttle bodies. Under certain conditions, one or more bolts could lodge in the throttle body area and interfere with the throttle linkage. If this happens during engine operation, the throttle may not be capable of returning to the idle position. This could result in an accident with the potential of personal injury or death to the operator, passengers, and or bystanders.

What Yamaha and your dealer will do: Your dealer will inspect the fuel tank filler hose on your Boat and will correct its installation if necessary. Your dealer will also inspect the air boxes on both engines on your Boat and will remove extraneous bolts if found. These services will be performed without cost to you for parts or labor.

What you should do now: Please call your authorized Yamaha Boat dealer to make a service appointment to have this procedure performed. Remember to take this letter with you when you take in your boat. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha web site at: www.yamaha-motor.com.

You should not operate the Yamaha Boat shown on the label above until this inspection/correction is performed.