

2004 SJ700B-C

FACTORY MODIFICATION CAMPAIGN – Possible Fuel Leak Yamaha Technical Bulletin WR2003-014

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a defect relating to vehicle safety may exist in certain 2004-model SJ700B-C “SuperJet” WaveRunner® watercraft. This bulletin was originally released on December 5, 2003.

Affected Models

2004 SJ700B-C F1N-0503171 ~ 0503440

The reason for this recall: In affected units, fuel could leak into the engine compartment due to a possible pinhole in the fuel tank wall. The fuel tank wall in affected units could be less than factory specification due to a manufacturing error. If leaking fuel or its vapor is subjected to an ignition source, there is a possibility of fire or explosion with resulting personal injury or death.

What Yamaha and your dealer will do: To correct this possible defect, Yamaha is initiating a Factory Modification Campaign. All units in the affected range must have the fuel tank replaced with a new one. There will be no cost to the customer for this repair.

What you should do now: Do not operate affected WaveRunner watercraft until they are modified.

If you are not the first owner of the watercraft and are unsure if this modification has been done, contact any authorized Yamaha Motorsports Dealer to check. Any authorized Yamaha Motorsports Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.