

**2010 SXT1800A-J/ B-J/ C-J/ D-J/ E-J/ F-J/ G-J/ H-J
FACTORY MODIFICATION CAMPAIGN – Dashboard Reinforcement
Yamaha Technical Bulletin B2010-002R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a possible defect which relates to safety may exist in certain 2010 AR240 HO (SXT1800A-J/B-J/C-J), SX240 HO (SXT1800D-J/E-J/F-J), 242 Limited S (SXT1800G-J), and 242 Limited (SXT1800H-J) model boats. This bulletin was originally issued on June 9, 2010

Affected Models:

2010 AR240 HO

SXT1800A-J F2D-0710101~0710186

SXT1800B-J F2D-0720101~0720190

SXT1800C-J F2D-0730101~0730175

2010 SX240 HO

SXT1800D-J F2D-0740101~0740175

SXT1800E-J F2D-0750101~0750170

SXT1800F-J F2D-0760101~0760162

2010 242 Limited S

SXT1800G-J F2D-0770101~0770438

2010 242 Limited

SXT1800H-J F2D-0780101~0780156

The reason for this recall: In affected boats, there is a potential for the dashboard to become dislodged from the helm compartment on the deck. If this happens while the boat is underway, it could cause interference with the control and handling of the boat resulting in injury or death to the operator, passengers, or bystanders.

What Yamaha and your dealer will do: To correct this defect, your authorized Yamaha dealer will install reinforcement brackets inside the dashboard to eliminate the possibility of the dashboard coming loose. The modification itself takes approximately one hour and 45 minutes to perform, although your dealer may need to keep your boat longer depending upon their schedule.

What you should do now: Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your boat for this service. Remember to take this letter with you when you take in your boat.

You should not drive your Yamaha boat until this modification is performed.

If you are unable to return to the Yamaha dealer who sold you the boat, this service will be performed by any authorized Yamaha Boat dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha web site at: www.yamaha-motor.com.